

TO BE FILLED BY THE INSPECTING OFFICER

1. Name of School : SANJOSE ENGLISH MEDIUM SCHOOL,
TALIPARAMBA
2. Name of Officer : GEORGE THOMAS CHIRAYIL
3. Location : TALIPARAMBA, PULIMPARAMBA
4. Period for which the certificate is issued : 2022-23
5. Types of building : RCC STRUCTURE

6. Nature of defect if any

- a) Foundation and basement
- b) Super structure
- c) Doors and windows
- d) Wood work wrought and put up
- e) Roof
- f) Flooring
- g) Miscellaneous

GF - 1206.75 m²
FF - 1169.36 m²
SF - 1169.36 m²

NIL

7. Any major defects notice which will render the building unsafe in any manner

8. Whether maintenance works have been done properly

YES

9. Whether the structure is sound for conducting

YES. SAFE UNDER NORMAL WEATHER CONDITION UPTO MARCH 2023

Note: 1. The stability of the structure should be examined also with reference to the altitude, intensity of wind exposure to flood etc.

2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate


Certified that the School was inspected by on 20/11/22 and found to be fit to conduct classes for the period for the reasons stated above

Place :

Date :

Taliparamba

20/11/22



Signature
George Thomas Chirayil
Designation: 875207
MUNICIPAL ENGINEER
TALIPARAMBA MUNICIPALITY

Principal

PRINCIPAL
SANJOSE ENGLISH MEDIUM SCHOOL
CBSE AFFILIATION No: 930259
TALIPARAMBA P.O., KANNUR DIST
KERALA, PIN: 670 141

**TO BE FILLED BY THE INSPECTING OFFICER
(Assistant Engineer/Assistant Executive Engineer)**

Name of School : SANJOS English Medium School, Taliparamba
 1 Name of Officer : Balakrishnan K.M.
 2 Location : Taliparamba
 3 Period for which the certificate is issued : Up to 31st March 2023
 4 Types of building : Permanent R.C.C.

Block I

Cellar Floor
3.70x10.15x3.72 M (Toilet Area)

G.F.

F.F

1)	G.F.	1)	F.F
	6.75 X 6.15 x 3.72 M 4 Nos. (Class Room)		6.75 X 6.15 x 3.72 M 4 Nos. (Class Room)
2)	14.15x2.15x3.72 M (Front Varandah)		3.20x6.15x3.72M (Store Room)
3)	17.30x2.15x3.72 M (Front Varandah)		34.62x2.15x3.72M (Balcony Front)
4)	14.15x1.45x3.72 M (Rear Varandah)		34.62x1.45x3.72M (Balcony Rear)
5)	17.30x1.45x3.72M (Rear Varandah)		3.05x6.15x3.72 M (Stair case)
6)	3.05x6.15x3.72 M (Stair case)		

Block II

Cellar Floor
31.40x11.35x3.72 M (Library)
4.80x17.55x3.72 (Toilet + Urinal

G.F.

F.F

1)	G.F.	1)	F.F
	6.70 X 6.10 x 3.72 M 4 Nos. (Class Room)		31.40x2.2x3.72 M (Varandah)
2)	31.40x2.00x3.72M (Varandah)		3.67x6.30x3.72 M (Stair Room)
3)	3.25x2.05x3.72M (Store)		
4)	3.27x6.50x3.72M (Stair Case)		

- 5 Nature of defect if any
- a) Foundation and Basement : Nil
- b) Superstructure : Nil
- c) Doors and Windows : Nil
- d) Wood work wrought and put up : Nil
- e) Roof : Nil
- f) Flooring : Nil
- g) Miscellaneous(Cracks if any) : Nil




 PRINCIPAL
 SANJOS ENGLISH MEDIUM SCHOOL
 CBSE AFFILIATION No: 930259
 TALIPARAMBA P.O., KANNUR DIST
 KERALA, PIN: 670 141

- 6 Any Major defects noticed which will render the building unsafe in any manner No
- 7 Whether maintenance work have been done properly Yes
- 8 whether the structure is sound or not for conducting classes Yes, The structure is safe for conducting classes under normal wind and weather condition


- Note:
- 1 The stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc.
 - 2 Any additional observation deemed necessary for the certificate may be furnished separately with the certificate

Certified that the School was inspected by me on ~~29.12.22~~ And found to be fit /unfit to conduct classes for the period for the reasons stated above.

Place: Thaliparamba
Date: 29.12.2022



Signature
Designation
ASSISTANT EXECUTIVE ENGINEER
LID & EW SUB. DIVISION
TALIPARAMBA BLOCK PANCHAYATH



Principal
SANJOS ENGLISH MEDIUM SCHOOL
CBSE AFFILIATION No: 930259
TALIPARAMBA P.O., KANNUR DIST
KERALA, PIN: 670 141